

RELEASE 11.0.2568

BUGIFX

- Fixed server crash that was caused by CGI strings with particular characters.
- Fixed crash caused by an erroneous request to play an EDGE track of an AXIS camera.
- Fixed the problem related to the persistence of auditing events, an incorrect parameter was shown in the configuration
- Fixed NEXT crash on closing the "Event Properties" window.



BUGIFX

• Fixed issue with scheduled notifications: now if you set a scheduled notification on a camera, it only affects the selected camera. Previously, the setting was erroneously "extended" to all cameras.

RELEASE 10.11.2384

- Wisenet compatibility extended to the SPE-1610 model
- Fixed problem on Mobotix decoder that caused problems with the reverse playback
- Fixed issue on the Native player that prevented exportations in case of gaps in the recorded video aroung midnight.
- Fixed an issue that could cause a crash at the end of a recoded exportation made with the native player.
- Fixed a crash that could happen when using the reverse plaback.
- Fixed a bug that could cause the accelerated play to stop (16x/32x).



- Fixed a Next crash caused by double clicking on the awl of a camera in the connector view
- Resolved crash that could happen when searching for a recorded video
- Next deadlock fix



- Fixed some playback problems occurring on the Native Player
- Fixed deadlock on the smtp server configuration for emails
- Fixed problem that occurred when adding a domain user that caused a server crash
- Fixed problem related to the user password change
- Fixed a crash on Next Portable
- Improved refresh of the status of Bosch Task peripherals
- Improved Bosch Task license display, now it indicates correctly the system status even when peripherals are not reachable
- Fixed crash at server start related to a configured Bosch Task
- Corrected the automatic reset set for the External I/O in the event the state is "triggered" as an associated device
- Improved management of the MXPEG Mobotix decoder
- Widespread improvement of event search and recordings:
 - Results come faster and it is faster to clean up the data for a new search
 - the progress-bar is more precise and gives the expected results even from several servers
 - in case of an excessive number of events to show in the Event Log (> 5000), the most recent ones are selected, regardless of the origin server.
- The display of the recording "bars" related to continuous recordings in native export searches has been improved
- Fixed a problem on the playback of an event: the right event was opened but the recorded one might be referred to another previously opened event
- Fixed a deadlock on SmartSearch
- Fixed some crashes that could happen during the Arteco Server process shutdown
- Fixed problems with videowall controls to bring layouts to the front
- Fixed the bug where an export was performed by entering the file name, but the file could not be found in any folder
- Fixed some problems on the player when increasing and decreasing the playback speed
- Removed Wanco telemetry and everything related to Wanco
- Fixed the ONVIF-G request for the replay of remote tracks: tested both on NVR HIKVISION, on BOSCH with Edge-SD and on Wisenet Hanwha with Edge-SD
- Introduced a new message for the user in case of missing or partial video exportation
- Removed the Chat Audio for communication between Next and Server
- Removed SMS notification
- Fixed updating in real time of peripherals in the Event Properties panel. Note: now the status of the peripherals has changed its position on the interface, it is located above the notes section.



- Fixed: "Ghost layout" problem when logging out of a server while viewing a remote layout.
- Added the ability not to perform and view the search for remote ONVIF recordings for NVRs
- The "Play in time UTC" parameter has been added to the interface to search for remote ONVIF recordings for the NVRs. This parameter could be required for some devices.
- Removed audio support for analog cameras
- Removed support for Polish and German languages
- Fixed problem that occurred when disabling the secondary stream in ONVIF profiles while it was set as a live profile on the layout: the channel was restarted continuously
- Fixed a problem on video playback when in the transition from pause to play: the play did not restart
- Fixed the redraw of the focus frame (green border on the selected view) in the views containing maps and devices
- Fixed a problem on the digital zoom from the toolbar curtain.
- Corrected a problem related to the start of the video analysis in case of enabling of the Enabling / Disabling Input plugins, Concatenated I / O and Associated I / O.
- Fixed a problem on the Boost export starting from a native export with the Privacy area: it was not possible to perform the Boost export.
- Fixed an issue on refreshing the status of an Everywhere in case it goes offline: it is now displayed correctly



- Removed Axis A1001 peripherals from the next and from the server, they will not be managed even for old servers
- Fixed incorrect deletion of events while deleting an edge backup track
- Fixed a problem with the display of cameras having the same name in the browser
- Fixed an issue on the list of auditing events for domain users
- Fixed some bugs that could cause Server crash
- Fixed a next crash caused by a problem in the configuration framework of ONVIF profiles
- The field containing the none of the ONVIF sources connected to the profiles has been enlarged
- Fixed an issue with the management of the video export progress bar
- Fixed a problem with the design of the browser bars in the case of NVR channels



NEW AUDITING FEATURES

Added new event types that will be tracked in the Auditing section

- Enable/Disable video channel
- Enable/disable camera plugin
- Enable/disable camera plugin scheduler

Plugins affected:

- 1. Abandoned/Removed Object
- 2. Violated Area
- 3. Privacy blur filter
- 4. Area Exclusion
- 5. Perspective

Plugins NOT affected:

- 1. LPR
- 2. I/O Event generation
- 3. I/O Enabling control
- 4. Chained I/O

- Next: fixed issues related to buttons "skip to next event" and "skip to previous event"
- Next: fixed issue related to the SmartSearch in the Roles Features section
- Server: Fixed problem with NVR HIKVISION related to the use of "summer time" time zone
- Server: Improved the playback start time calculation when it was asked to play a remote track on the NVR
- Next: Removed the menu "Notification scheduler" for Servers with older software versions. The feature is available only with Servers having version 10.9.2268 or latest.



RELEASE 10.9.2268


EVENT NOTIFICATIONS SCHEDULER

We added the possibility to schedule the Event notifications. This feature is based on the Schedule calendar already available for other features, and allows the administrator to decide when to view/receive notifications and when to "silence" them instead.

IMPORTANT: If the notifications are silenced, those will still be recorded in the database and therefore it will be possible to search for them later in the recording environment. It is therefore a muting, which in any case will allow operators and administrators to search for events that have not been notified.

NOTES

- 1. It will not be possible to set diversified schedules, or activate / deactivate calendars for a single notification (log, app, output ...). The scheduling of the calendar will have an impact on all the notification methods provided for the device.
- 2. The Event notifications scheduler is available for devices in the video channel section and peripherals, but not for server events.
- 3. It is possible to use the Multiple selection (of devices of the same type) to configure the Event notification scheduler.





RELEASE 10.8.2267

BUGFIX

• Fixed a memory drift by modifying the cleaning procedure at night.



RELEASE 10.7.2265

NVR EDGE RECORDINGS ACCESS

We added the possibility of accessing and exporting the tracks recorded on remote support (Edge recordings) of the NVR Onvif compliant, directly from Arteco NEXT.

The Arteco platform, already able to receive live audio / video streams from these devices, also allows you to manage the recordings on the NVR, using Onvif protocols. Thanks to this new functionality of the ARTECO VMS, it therefore becomes possible:

- 1. search for the recordings stored on the NVR
- 2. view and play the EDGE NVR track in the Arteco-NEXT browser
- 3. automatic import and consolidation of EDGE NVR tracks in Server recordings (cable disconnected automatic edge retrieval)
- 4. manually import and consolidate EDGE registrations in Arteco Server registrations
- 5. export directly to the client pc the EDGE trace present on the NVR device

A peculiarity that can be highly appreciated by those who want to manage these systems remotely, but do not have a high performance connection between the Arteco VMS and the recorder, is the possibility of doing all of this described in point 1) even in "channel" conditions. off "on the Arteco VMS, thanks to the" video inhibition "function.

We will shortly provide as comprehensive a list of compatible NVRs as possible. However, it will be a list that is continuously updated.

I/O CONVERTED INTO PERIPHERALS

Following the introduction of the Peripherals section, and at the same time the less and less frequent use of the I/O devices, it was decided to eliminate the I/O section from future releases.

In case of version update, some I/O devices will be automatically converted into Peripherals.

Some others, see table below, will be permanently eliminated and consequently not converted.

IO DEVICE	PERIPHERAL
Arteco Serial	Not converted
Axis I/O	Converted in AXIS I/O in the peripheral section
Virtual	Converted to External IO with any extensions Neither the calendar nor the default state of the virtual* variable will be converted
Mobotix	Not converted
Samsung	Converted in "Samsung I/O" in the peripheral section
Arteco Ethernet Remote	Arteco Everywhere (default states will not be converted)
CIAS I/O	Not converted



Smart IP Controller	Arteco Everywhere (default states will not be converted)
Arteco Everywhere	Arteco Everywhere (default states will not be converted)

Note

- 1) No notification settings are converted when switching from I / O to Peripheral. In particular, associations are lost if the I / O were defined in the notifications of:
 - Peripherals
 - Cameras
 - Server
- 2) I/O Default States have not been converted
- 3) The Pushpins on the Maps have not been converted
- 4) The Output Pin for all Plugins have not been converted (violated area and abandoned / removed object)
- 5) Output calendars have not been converted
- 6) The I / O pins associated with the PTZ presets have not been converted to Peripheral

Where possible, the references that the cameras have in the Input Output Plugin section (Event generation/ Enabling control and Chained) have also been converted.

Exceptions are the old Linked I/O associated with video analysis plugins whose association has not been converted because it has been implemented as described in the next point ("Associated I / O Plugin Creation").

ASSOCIATED DEVICES

The "Associated devices" plugin has been created, which allows you to associate a Peripheral (output) to a Camera and to control its status from live with the right button shortcut -> associated device.



This feature is available for ARTECO NEXT and will also be implemented soon on Web Access and App.



LOCATE DEVICE

A new function is now available to locate on the ARTECO NEXT device tree a device starting from the visualization of the object on a map or on Open Connector.Right clicking and selecting "Locate device" the selection on the tree moves to the pointed device.

- NEXT: now the label numbers of the "External States" device are consistent
- SERVER: the search filter in the Database has been restored to obtain the events associated with the cameras only
- SERVER: a malfunction in the removal of an ONVIF camera has been corrected
- SERVER: fixed a malfunction in the stamp maker that occurred when the resolution of the substream of a camera was high
- SERVER: fixed a malfunction that could occur while writing an Auditing event
- SERVER: a problem that could occur during the search for events in the Event Log panel has been resolved (the colors were not shown correctly)
- SERVER: a defect in the lack of visualization of the representation bars of the recordings has been corrected
- SERVER: now writing events to the Database correctly reports the result of the operation
- SERVER: The periodic cleaning of the Registration Sessions (PurgeSessions) has been temporarily disabled as it could cause an overload.
- SERVER: Corrected a problem on the duplication in configuration of the "cleaning / schedule" node of the peripherals.
- SERVER: Resolved a resource allocation problem in the DB that caused event queries to fail.



RELEASE 10.5.2243

MOBILE DIGEST

Introduced the DIGEST mode for encrypted login for iOS, Android and web access applications

- Fixed crash of NEXT on autologin from concurrent clients with the same user from different locations. Now if the forced logout occurs, the Next interrupts the autologin: the automatic login is disabled, for the server in question, until the next restart of the NEXT client.
- Corrected problem in case of expired Registration-code as the NEXT did not allow any operation on the server.
- Fixed problem on the dewarping with adaptive resolution set. Switching from the secondary to the primary and vice versa the view settings are now reset every time to allow proper operation of the dewarp. The correction on the dewarp has been extended to the case in which the profile is reset from the context menu.



RELEASE 10.3.2212

LPR SNAPSHOTS ON DB

We implemented a new way of storing LPR snapshots. While once a "snapshots" sub-folder was created in the path of the camera recordings, vice versa now the image is saved in the DB.

SNAPSHOT EVENT PREVIEW (OMNIA)

If the live snapshots profile is active on the camera, every time a video event of a camera is created, the snapshot is saved in the DB.

This image can be recovered only with the Omnia project and not with the current Next.

IMPORTANT NOTE

The numbering of the software versions has been changed: the first number is progressive and linked to the year, the second number is linked to the introduction of new features. The information of the Quarter has been eliminated, from now it won't be available anymore.



RELEASE 10.0.1.2209

- Fixed problem on native export which did not allow to export the auxiliary recording track: when doing so the main track was provided instead.
- Fixed problem on contextual menu of live profiles introduced with the TURN ON VISUAL DETAILS feature: it was not possible to change the default profile in live.
- Fixed server crash problem when closing RTSP stream channels having failures.



RELEASE 10.0.1.2202

SHOW LICENSE EXPIRE DATE

The SERVER INFO page from the SETUP menu of the NEXT now displays also the expiration date of the server license

TURN ON VISUAL DETAILS

Added a command to the context menu of the live views to enable or disable commands for displaying all the details of the Arteco analysis.

VIRTUAL MACHINE LICENSE UNLOCK

Removed the license constraint on hardware keys for servers installed on virtual machines. Upon authorization from the Management, production can issue licenses for virtual machines.

ARTECO CONSOLE UPDATED

Updated the Console with new features and new shortcuts useful for support and troubleshooting

BUGFIX

• fixed a problem related to the conversion of recordings from Firebird to MariaDB for network paths (eg NAS).



RELEASE 10.0.0.2197

EVENT DB RETENTION

The deletion of video events from the DB is carried out on the basis of a specific and configurable retention, with a dedicated procedure, different from the cancellation of the video. In this way, the archiving of channel events has been aligned to the management of all other types of events. Once a day the cleaning operation will be performed and events older than the retention value will be deleted from the DB.

- Fixed an issue that could prevent successful database creation on startup. This version corrects any errors generated by previous versions.
- A new DB error checking procedure has been introduced: if non-repairable errors are detected, the server documents the error in the LOG file and stops to avoid data loss
- The database conversion process has been speeded up and some conversion bugs have been fixed.



RELEASE 9.3.3.2168

DB CONVERTER

The video archive acquisition phases and previous events have been optimized in case of updating a server with old database: now the process takes place in significantly shorter times.

OC ROI ADAPTATION TO BOUNDING BOX

Any ROIs contained in an Open Connector event have been compared to the bounding boxes produced by ARTECO video analysis, and are now processed in the same way:

- have been integrated into the flow of metadata produced by video analysis and are saved in the same way as the the bounding boxes produced by standard Arteco analysis to ensure that they are reproduced by the player in the same way
- 2) a violated area event will be generated, containing information related to the Connector that produced the event in the description field. The event is "centered" on the time interval covered by the ROI flow and the event play displays all the metadata associated with the latter, similarly to what occurs during the playback of any event.

The generation of the video event and therefore the possibility of inserting it in the Smart Search searches requires the appropriate license.

- Fixed a refresh issue in the Open Connector configuration GUI
- Fixed problems related to configuration and sending of custom commands for the Open Connector.



RELEASE 9.3.2.2132

VIDEOWALL – FRONT LAYOUT CONTROL

With this feature, we allow an "A" client to control the display of layouts on a "B" client, or, more in detail, ensure that a "A" client can bring a layout to the forefront of another "B" client shared remote on one of the windows opened by client "B".

Through the "device properties" panel of a shared remote layout, we introduced a set of controls that allow to carry out the above operation on one of the current clients logged on to a given server. The client of the operator who sends the request must obviously belong to this group of clients.

Informazione I	Layout:			
Server:	DCAV [local	host:7000]		
Nome:				
ID:	6			
Tipo:				
Dispositivi Ass	0(
	nal State 01 nal State 02			
1	2			
5	6	7	8	
Visualizza sull PCAdmin	la postazione:		•	1) Client station selection
Nella finestra Faenza Cel			•	2) Window selection
	Porta in pri	mo piano		3) Confirm

The client will be selected using a combo-box containing the list of client stations logged onto the server. As a consequence, it will be possible to send the request to only one client at a time.

Then, it will be possible to populate a specific window of that client station.



Notes

- Currently, if the "Device properties" panel is not visible, it can be opened using the command View -> panels -> device properties of the main menu: in order to simplify these operations, this command will be added with a right mouse button on a device and, in the specific case, on the Shared Layout.
- Starting from now, the "Device properties" panel will be active for all hierarchical levels, so also Users will be enabled to perform drag & drop of a layout.
- An important aspect not to be underestimated concerns the sending of this command to windows where the active environment is SETUP or REC: the NEXT will prevent the movement of a layout on a window where one of these environments is active.
- A final aspect concerns the interaction of this command with the PATROL and POPUP settings: no specific limitations will be introduced even if the combination of popups or patrols with the video wall must be avoided.
- As for the license, nothing will be changed: everything will be available with the videowall license of already existing shared layouts.
- To facilitate the selection operations, clients will be offered the possibility of acquiring a more precise identity, or rather of a descriptive name similar to that which can be assigned to the servers, thus assuming the actual role of stations. If the administrator does not assign the name, the default PC and window names (Windows name of the host PC and "MAIN WINDOW" for the main window and "WINDOW 1", "WINDOW 2", ... "WINDOW N" for secondary windows)




RELEASE 9.3.0.2126

RECORDINGS PROTECTION

The Recordings Protection function allows you to protect parts of recordings from self-deletion. Then, any Protected recordings will be deletable only manually.

This feature is available by using a new button in the Recording Browser bar. This Button will appear only if a single camera is selected and if the user is enabled for the "Export Recording" rule (default for administrator and power user).

Below is an example of selecting a portion of Registration:



As soon as a part of the recording will be determined, through the button will be possible to protect the recorded video.

Recordings Browser	Ț× ▶ ▶ ▶ ► ♥ © ⊟ ® I II 🖆 ৫ 吗 🖪
ora solare Europa occidentale	10/30/19 12:00 PM Protect Recordings 06:00 PM
+ 3S .5.150 PTZ	
	× >
Event Log Recordings Browser	



Protect Recording	js	×
Protection Interval —		
Start Time:	30/10/2019 🔷 13:03:34	
End Time:	30/10/2019 🚔 17:57:02	
Source:	3S . 5. 150 PTZ	
	OK Cancel	

Once you have pressed "ok" the protection procedure will be started and this will result in a final message highlighting the initial and final instant of the protected recording.

ARTECO-LOGIC-Next	
Successfully protected recording chuncks from 30/10/19 13 30/10/19 18:03:57 for "3S .5.150 PTZ"	:01:55 to
	ОК

The protection of a portion of the recording will be at the level of the single ".eye" file. This means that, if you select a recording portion for protection, the actual protection will be a larger section (or at most equal), since it depends on the size of the file or files that belong to the interval selected by the user.

Following the protection operation there will be no way to highlight the protected parts. To be able to eliminate the protection it will be necessary to delete the recordings using the "delete registration" button.

As a corollary of the project, the self-cancellation function is eliminated, which we believe is no longer necessary and useful.

Paths	PathId	Types 🔻	Total Size (GB	3) Assign	d Space (GB)	Allocated Space (G	B)	Channels	Defau	Reversible E	Errors Failover
D:\rec-aux\	d:2	AUX	1769	255		255		15	NO	YES	
C:\programdata\arteco-server\data\rec\	c:2	DATA	884	200		0		0	YES	YES	
D:\recording\	d:0	DATA	1769	1000		999		8	NO	YES	
E:\recording\	e:0	DATA	1769	1000		999		7	NO	YES	
D:\spare\	d:1	SPARE	1769	500		0		0	NO	YES	
E:\spare\	e:1	SPARE	1769	500		0		0	NO	YES	
Auto Balance	Add New Pa	th Del	ete Selected Path	Ì							
Sources	PathId	Delet	te Type	Assigned Space	[GB] Rec	. Enabled	T, t	Delete	AutoDelete E	By Days	Days
Arteco Face Recognition	d:2	AUTO	1	17	YES		YE		NO		0
ARTECO VEMS	d:2	AUTO	1	17	YES		YE YES		NO		0
Entrance Hall (Wisenet X)	d:2	AUTO)	17	YES		YES		NO		0
Entrance Hall - Analytics Extreme	d:2	AUTO	1	17	YES		YES		NO		0
Intercom (2N)	d:2	AUTO	1	17	YES		YES		NO		0
Meeting Room Fisheye 360° (ORCA)	d:2	AUTO	1	17	YES		YES		NO		0
Perimeter - Analytics Extreme	d:2	AUTO	1	17	YES		YES		NO		0
Perimeter - Backdoor (Bosch)	d:2	AUTO	1	17	YES		YES		NO		0
Perimeter - Gate (Axis)	d:2	AUTO	1	17	YES		YES		NO		0
Perimeter - Main Entrance (AXIS 5-MPixel)	d:2	AUTO)	17	YES		YES		NO		0
Perimeter Defender (Axis)	d:2	AUTO	1	17	YES		YES		NO		0
PTZ Top Roof (Bosch)	d:2	AUTO	1	17	YES		YES		NO		0
✓ Stairs (Axis)	d:2	AUTO	1	17	YES		YES		NO		0
Traffic Road - ET	d:2	AUTO	1	17	YES		YE		NO		0
Training Room - AC	d:2	AUTO	1	17	YES		Y,		NO		0



BUGFIX

- It is now possible to connect to Onvif cameras configured accessible via internet and configured on different sub-networks
- Resolved issues related to excessive consumption of resources when managing IP video sources with H.265 encoder
- Fixed some incompatibility problems of Wisent PTZ (PNM-9320VQP) configured as Onvif
- Correction of the label related to the Smart Search search result
- Fixed problems installing the 32bit SDK. Remember that the SDK package is 64bit but can be installed at 32bit depending on what the customer decides.
- Added messages to the video export report dialog: these messages show the export fps deriving from the recorded flow. Below 10fps there could be export problems.
- Fixed a error handling in the SmartSearch
- Fixed a problem on using the 32bit Next installed with the 32bit server suite.
- Fixed a problem related to disconnection of a view on the layout, which was un-removable if the server was offline.
- Fixed a software conflict that could occur between the layout Patrol and the Popup mode. Now it is no longer possible to activate Patrol and Popup on the same window.

NOTE:

Our Software Suite as well as Arteco NEXT is compatibile only with Windows 64-bit operating system

In order to grant compliancy towards analog frame-grabber cards, it is allowed to install the 32bit package "Arteco Suite X86" on native 64bit OS only as detailed in the list below

OS

Windows 10; Windows 8.1; Windows 8; Windows 7 Service Pack 1; Windows Server 2016; Windows Server 2012; Windows Server 2008 R2 SP1; Windows Server 2008 Service Pack 2

- RAM: 8GB or higher
- CPU: i3 or higher
- HDD: at least 10GB available, 7200 RPM and minimum throughput 80MB/s



RELEASE 9.2.0.2110

SMART SEARCH

The Smart Search feature consists of being able to search for and view events that occurred in a portion of recorded video, within a defined area.

- The Smart Search is based on the Arteco video analysis (Violated Area and Removed/Abandoned Object), whose information is stored in the main recording stream, this means that you can have the Smart Search only for those channels where the "video analysis" was enabled in the selected period.
- The events that the Smart Search can identify are the same as those generated by the "Violate Area" and "Abandoned / Removed Object" plugin: the search result will show a subset of the events saved in the DB based on the area drawn.
 - It is therefore important to use the plugin filters well in order to find the most interesting events. This could on the one hand create a greater number of "false events" but could be useful for using the Smart Search.
- The greater the surface of the image covered by the analysis area, the greater the possibility of obtaining results with the definition of any Smart Search area.
 - o If the area covers the whole image I will get valid Smart results whatever the rectangle used.
 - Vice-versa, if the analysis area covers only half of the image I will get Smart results only if the Smart rectangle covers at least part of the analysis.

This second scenario is useful if we have to analyze only a portion of the image with the Smart Search: in this case it does not make sense to perform the analysis on the whole image, indeed it is more correct to do it only on the area of interest. Think of a fence near a motorway continuously traveled by vehicles, and you need to detect intrusions by people. In this case it is useful to define a sensitive Violated Area only on the fence because this helps to reduce the number of events generated and written in the DB.

It is also true that, in this way, if I apply the Smart Search to the motorway area I would not get any result.

Important note:

It may happen that expanding the sensitive area of motion can be many events generated by the plugins. To avoid this inconvenience it is advisable to disable notifications of events generated by the plugins.

License

The Smart Search feature is available for eMotion, Active and Extreme licenses. The license applies to the Server, this means that you can perform the Smart Search on all the cameras of a licensed server (as long as the Violated Area or Object Removed / Abandoned plug-ins are enabled on these).

Clearly, given the "limits" of the eMotion analysis filters, the Smart Search will be less efficient on this type of channel.

It is not possible to have the Smart Search for LPR channels as the Violated Area and Abandoned/Removed Object Control plugins are disabled.



USING SMART SEARCH

Smart Search can only be performed on one camera at a time.

It will therefore be necessary to be in the RECORDINGS environment and search for recordings based on the time frame required. After that:

- 1. Select a camera
- 2. Select the time interval (using the time bar activation button, as for the export)
- 3. Click on the highlighted button

Recordings Browser		BBI				Ψ×
ora solare Europa occidentale	07/30/19 0		03:15 PM	03:30 PM	03:45 PM	
+ Arteco Face Recognition		_				î
+ ARTECO VEMS		_				
+ Entrance Hall (Wisenet X)						
+ Entrance Hall - Analytics Extreme						

A screen will open that will allow the user to set an area to perform the search afterwards

	Smart Search		×
I ار	nfo		
	Start Time:	30/07/2019 🙀 15:02:32 🚔	
	End Time:	30/07/2019 💽 15:50:32 🚭	
	Source:	Entrance Hall (Wisenet X)	
	Area		
) E	Arteco-IT-Demo-1 Entrance Hall(Wisenet)	x)	
		Click here to design the ar the Smart Search	ea for
		OK Cancel	



Click OK once the Smart Search Area has been defined. As seen in the image above, a progress-bar appears identifying the time required for the search.

- The Progress bar will only be visible when the OK button is pressed.
- The Cancel button is always visible, and allows you to cancel the start of a search or the search itself.

The results of the research will populate the "Event Log" * panel. You will need to double click on the desired event to start the recording playback.

*if not in the foreground (the graphic browser is shown by default), this panel should be selected to be displayed.

CAMERA MANAGEMENT

Now the Wisenet PNM-9320VQP is supported

NOTE:

Our Software Suite as well as Arteco NEXT is compatibile only with Windows 64-bit operating system

In order to grant compliancy towards analog frame-grabber cards, it is allowed to install the 32bit package "Arteco Suite X86" on native 64bit OS only as detailed in the list below

OS

Windows 10; Windows 8.1; Windows 8; Windows 7 Service Pack 1; Windows Server 2016; Windows Server 2012; Windows Server 2008 R2 SP1; Windows Server 2008 Service Pack 2

- RAM: 8GB or higher
- CPU: i3 or higher
- HDD: at least 10GB available, 7200 RPM and minimum throughput 80MB/s



RELEASE 9.2.0.2110

NOTE:

Our Software Suite as well as Arteco NEXT is compatibile only with Windows 64-bit operating system

In order to grant compliancy towards analog frame-grabber cards, it is allowed to install the 32bit package "Arteco Suite X86" on native 64bit OS only as detailed in the list below

OS

Windows 10; Windows 8.1; Windows 8; Windows 7 Service Pack 1; Windows Server 2016; Windows Server 2012; Windows Server 2008 R2 SP1; Windows Server 2008 Service Pack 2

- RAM: 8GB or higher
- CPU: i3 or higher
- HDD: at least 10GB available, 7200 RPM and minimum throughput 80MB/s



RELEASE 9.1.1.2102

BUGFIX

- Fixed problem with changing existing username
- Fixed Onvif problem related to old generation cameras
- Fixed problem on cancellation of auxiliary routes
- Fixed problem with connection to Bosch Task and Wisenet I/O devices
- Resolved the management of the error message in the DB conversion in first installation
- Update system information on VC runtime installation
- Fixed a deadlock on the initialization of the following devices: Wisenet I/O, Bosch I/O, Bosch Task.
- Fixed a problem displaying the timeline on gray bars in the recording browser
- Fixed problem on the ArtecoMobile smart app to connect to multiple servers with the same public IP
- Improved behavior of advanced configuration in the Onvif Panel
- Fixed problems that prevented the use of the application on devices with Android 9.0
- Resolved issues with stretched images on WebAccess
- Fixed the installation package, now the http port is correctly defined

NOTE:

Our Software Suite as well as Arteco NEXT is compatibile only with Windows 64-bit operating system

In order to grant compliancy towards analog frame-grabber cards, it is allowed to install the 32bit package "Arteco Suite X86" on native 64bit OS only as detailed in the list below

OS

Windows 10; Windows 8.1; Windows 8; Windows 7 Service Pack 1; Windows Server 2016; Windows Server 2012; Windows Server 2008 R2 SP1; Windows Server 2008 Service Pack 2

- RAM: 8GB or higher
- CPU: i3 or higher
- HDD: at least 10GB available, 7200 RPM and minimum throughput 80MB/s



RELEASE 9.1.1.2080

NEXT PORTABLE

Implementation of the client in "executable" mode, to open the exported recordings in Native format.

At the time of exportation, you can also decide to export NEXT Portable.

Export Settings		×
Start Time:	27/08/2019	
End Time:	27/08/2019	
Source:	Dahua . 115	
Export Settings		
MP4 with Metadata		
MP4 or MKV Video +	Audio only (boost)	
Native Player Forma	ť	
Remove Privacy Mas	k 💟 Metadata	
Maudio Track	Overlay Date/Time	
Export Player		
Destination		
O Desktop		
Other		
File Name		
	OK Cancel	

An "Export" folder will be created, with the registrations inside and the connection to the client.

The client starts in this mode only if opened by the link in the Export folder, since it contains the "-externalplayer" parameter inside it. At startup, the NEXT Portable will prompt you directly on the Recordings page, find the automatically exported recordings and also search for them in the period from the beginning of the oldest recordings to the end of the most recent recording.

From now on, even exporting only the recordings, they will be encapsulated in two named folders \Export\recordings.

ONVIF PROFILE G

Introduced the support for the G profile of Onvif, which introduces the possibility of managing the recordings that may be stored on the cameras (edge recordings).

ar	eco	
🖌 Enable Recording		
Codec	Main H.264	•
Codec Resolution	1920 x 1080	
Continuous/Pre-Event	: Frame Rate	
		25
Quality		
-1	,	4
Show Machine ID at	nd Timestamp	
Record audio track		
<section-header> Retrieve Edge R</section-header>	ecording*	
Event Settings		
Pre-Event Recording (s	sec.)	3
Post-Event Recording	(sec.)	3
Post-Event Frame Rate	2	
		25

APACHE

Web Server Apache has been updated to the last version (2.4.39).

ARTECO MOBILE – ARTECO APPS

Thanks to the update, now it is allowed the identification of Servers with the same IP but on different ports.

RETENTION OF SERVER EVENTS

Retention for server events introduced.

DOUBLE PASSWORD

Implemented double password management with the introduction of a new management of export parameters:

- the BOOST export authorization is now linked to the permission to remove the privacy zones
- Users and Power User and user type can now export Native recordings, after entering Supervisor credentials. The Supervisor user is defined in the user configuration section.



Last Name		First Name vista		
Username vista		Rights		
Vista		Administrator		
Old Password	Password		Confirm Password	
Server Name [2077] Fitzcarraldo , 163 Museo Galleria Ester] 🔻	Available camera Dahua .115; Dauha Clier	is hte CV .5.63; Geo 💌	Recordings Supervisor	
Auditing				
Login and Logout	🛿 Add/Edit/Remove Use	rs	Add/Remove Devices	
Play Recordings	🗾 Play Events		🕑 Delete Recordings	
V Delete Events				
Add	Sa Sa	ve	Delete	

When entering the Recordings environment, if the user is a "power user" or "user", he will be asked to enter credentials for a Supervisor user. This step is not mandatory, in case these will not be inserted users and power users will be able to do their jobs, but without the possibility to export video in Native format.

Authorization R	equired
Some of the requested actions require high permissions. Enter the recordings supervisor credentials.	
Server Name	[2077] Fitzcarraldo . 163 Museo Galleria Estense [192. 168. 10. 163]
	Send credentials to all servers
Username	
Password	
Send Supervisor Credentials Exit Without Enabling Supervisor	

In any case, it will be necessary to enter the credentials of a different Supervisor user other than the one who is accessing (security layer required by GDPR privacy regulations).

BUGFIX

- Modified the composition of the cookie for mobile sessions: now the cookie also contains the codename of the server.
- Database update management. Before installation, the necessary patches for the update are now installed, and the database now has a "version number" which is checked at startup.
- Fixed problems that could prevent the database from being updated on 32-bit architectures.
- Fixed the behavior of the Onvif advanced configuration panel
- Fixed some possible problems that caused the Server to crash.
- Fixed the possibility to delete portions of registration for old servers, where the function was not yet entered.
- Fixed an error displaying server events: it also incorrectly included auditing events, but these are not events.

ARTECO RELEASE NOTES ENG



RELEASE 9.0.0.2061

- Fixed crash on Popup Cyclic mode
- Improved conversion from old to new DB
- Fixed a problem on deleting events from Event Log
- Introduced the possibility to export a video from the event log while in the Recording environment
- Fixed the insertion of metadata on a video source following the generation of Open Connector events
- Improved event search with parameter
- Fixed bug on the selection of calendar nodes in the REC environment
- Fixed bug on setting / removing privacy in the snapshots streaming
- Fixed problems with replaying recordings near a "hole"
- Fixed problem with event browsing in the record browser using the Previous Event vs Next Event buttons
- Fixed bug on self-deletion of auxiliary path recordings
- Correct fps reading for Wisenet cameras
- Correct cancellation of events on auxiliary tracks
- Fixed bug on registration "holes" in case of file change



RELEASE 9.0.0.1965

MARIA DB

We switched from Firebird-DB to Maria DB. This will allow for increased possibilities and faster access to events. The conversion of old events and recordings from old versions to the newest one is automatic, upon keeping the same configuration paths. The GUI and usability of the Arteco NEXT software remains the same.

AUDITING

Through Arteco NEXT, administrators are now allowed to "query" the and track the access to events made by other users.

MANUAL CANCELLATION OF RECORDINGS AND EVENTS

Administrators are allowed to delete portions of recordings based on specific time intervals.

As well, administrators are allowed to delete events from the Log Event panel and the DB, permanently.

SDK

During the installation, the wizard allows the user to choose between the 32 or 64bit architecture.

CAMERA MANAGEMENT

Added the ability to change the HTTP and RTSP ports for all camera brands that need these. Support for Lumenera brand removed.

- Fixed path of the Mobile log
- Android APP: at the app launch/startup a page will appear, informing users about the usage of data (in compliancy with the GDPR). To continue using the app you must accept the policy.